



Public Health Engineering Department

Government of West Bengal

Tender: NIT NO:18/ALD/2024-2025

1. General Information

Type	NIT	Category	Works	Mode	OFFLINE	Method	Open Tender
District	ALIPURDUAR		Inviting Authority		Executive Engineer, Alipurduar Division		
Tender Reference	NIT NO:18/ALD/2024-2025	Estimate Put to Tender	93791.00	Memo No	3509/ALD	Memo Date	03-10-2024
e Tender Id		Description	Repairing of Pump House at HEADWORK site of TAPSHIKHATA PWSS Under Alipurduar Division PHE DTE.				
Estimated Work Value	-						

2. EMD (Earnest Money Deposit) Details

Exempted?	No	Fee Type	Payable To	Payable At
-----------	----	----------	------------	------------

3. Critical Dates

Tender Publish Date	03-10-2024 02:00 PM	Sale/Submission Start Date	
Download Start Date		Sale/Download End Date	25-10-2024 02:00 PM
Last Date of Application	23-10-2024 02:00 PM	Last Date of Permission	
Last Date of Submission	25-10-2024 02:00 PM	Tech Bid Opening Date	
Fin Bid Opening Date		Tech Bid Uploading Date	
Uploading Bid Date Time		Time	

4. Pre-bid Meeting Details

Date	Venue	Address
------	-------	---------

5. Work Details

Sl No	Description	Estimated Cost (Rs.)	Completion Time	EMD (Rs.)
1	Repairing of Pump House at Headwork site of Kaijali Basty PWSS Under Alipurduar Division PHE DTE.	93892	60 DAYD	2% OF ESTIMATED AMOUNT
2	Repairing of Pump House at 2nd TW site of Kaijali Basty PWSS Under Alipurduar Division PHE DTE.	92144	60 DAYD	2% OF ESTIMATED AMOUNT
3	Repairing of Pump House at HW and 2nd TW site of SALSALABARI PWSS	96884	60 DAYD	2% OF ESTIMATED

	Under Alipurduar Division PHE DTE.			AMOUNT
4	Repairing of Pump House at HW site and 2nd TW site of Jashodanga PWSS Under Alipurduar Division PHE DTE.	96016	60 DAYD	2% OF ESTIMATED AMOUNT
5	Repairing of Pump House no1 at HW site of SAMUKTALA PWSS Under Alipurduar Division PHE DTE.	96617	60 DAYD	2% OF ESTIMATED AMOUNT
6	Repairing of Pump House no 2 at HW site of SAMUKTALA PWSS Under Alipurduar Division PHE DTE.	96115	60 DAYD	2% OF ESTIMATED AMOUNT
7	Repairing of Pump House at 2nd TW site of PURBA CHEPANI PWSS Under Alipurduar Division PHE DTE.	85097	60 DAYD	2% OF ESTIMATED AMOUNT
8	Repairing of Pump House at 2nd TW site of BAKLA PWSS Under Alipurduar Division PHE DTE.	95437	60 DAYD	2% OF ESTIMATED AMOUNT
9	Repairing of Pump House at 3rd site of BHATIBARI PWSS Under Alipurduar Division PHE DTE.	96698	60 DAYD	2% OF ESTIMATED AMOUNT
10	Repairing of Pump House at 2nd site of SALKUMARHAT PWSS Under Alipurduar Division PHE DTE.	78338	60 DAYD	2% OF ESTIMATED AMOUNT
11	Repairing of Pump House at 2nd TW site of TAPSHIKHATA PWSS Under Alipurduar Division PHE DTE.	78338	60 DAYD	2% OF ESTIMATED AMOUNT
12	Repairing of Pump House at 2nd TW site of PAITKAPARA PWSS Under Alipurduar Division PHE DTE.	78338	60 DAYD	2% OF ESTIMATED AMOUNT
13	Repairing of Pump House at 3rd site of DAKSHIN SONAPUR PWSS Under Alipurduar Division PHE DTE.	82769	60 DAYD	2% OF ESTIMATED AMOUNT
14	Repairing of Pump House at HEADWORK site of PAITKAPARA PWSS Under Alipurduar Division PHE DTE.	93791	60 DAYD	2% OF ESTIMATED AMOUNT
15	Repairing of Pump House at HEADWORK site of SALKUMARHAT PWSS Under Alipurduar Division PHE DTE.	93791	60 DAYD	2% OF ESTIMATED AMOUNT
	Repairing of Pump House at HEADWORK site of TAPSHIKHATA PWSS Under			2% OF

16	Alipurduar Division PHE DTE.	93791	60 DAYD	ESTIMATED AMOUNT
17	Repairing of Pump House at HEADWORK site of BIRPARA (APD) PWSS Under Alipurduar Division PHE DTE.	93791	60 DAYD	2% OF ESTIMATED AMOUNT
18	Repairing of Pump House at HEADWORK site of MUNSHIPARA PWSS Under Alipurduar Division PHE DTE.	93791	60 DAYD	2% OF ESTIMATED AMOUNT
19	Repairing of Pump House at 2nd site of BIRPARA (APD) PWSS Under Alipurduar Division PHE DTE.	78339	60 DAYD	2% OF ESTIMATED AMOUNT
20	Repairing of Pump House at 2nd TW site of MUNSHIPARA PWSS Under Alipurduar Division PHE DTE.	78339	60 DAYD	2% OF ESTIMATED AMOUNT
21	Repairing of Pump House and Boundary wall at Headwork site of Lokhnathpur PWSS Under Alipurduar Division PHE DTE.	92727	60 DAYD	2% OF ESTIMATED AMOUNT

6. Attachments

Sl No	File Name
1	SL3.pdf
2	SL1604102024203503.pdf
3	Notice 1804102024202025.pdf
4	SL7.pdf
5	SL4.pdf
6	SL12.pdf
7	2911ii.pdf
8	SL10.pdf
9	SL9.pdf
10	SL13.pdf
11	SL1804102024203313.pdf
12	SL2.pdf
13	SL8.pdf
14	ANNEXURE.pdf
15	SL2004102024203108.pdf
16	SL1704102024203410.pdf
17	SL11.pdf
18	SL6.pdf

19	SL1.pdf
20	SL14.pdf
21	SL5.pdf
22	SL1504102024203552.pdf
23	SL2104102024203016.pdf
24	SL1904102024203215.pdf