



Public Health Engineering Department

Government of West Bengal

Tender: NIT NO:18/ALD/2024-2025

1. General Information

| | | | | | | | |
|----------------------|-------------------------|------------------------|--|---------|---|-----------|-------------|
| Type | NIT | Category | Works | Mode | OFFLINE | Method | Open Tender |
| District | ALIPURDUAR | | Inviting Authority | | Executive Engineer, Alipurduar Division | | |
| Tender Reference | NIT NO:18/ALD/2024-2025 | Estimate Put to Tender | 96884.00 | Memo No | 3509/ALD | Memo Date | 03-10-2024 |
| e Tender Id | | Description | Repairing of Pump House at HW and 2nd TW site of SALSALABARI PWSS Under Alipurduar Division PHE DTE. | | | | |
| Estimated Work Value | - | | | | | | |

2. EMD (Earnest Money Deposit) Details

| | | | | |
|-----------|----|----------|------------|------------|
| Exempted? | No | Fee Type | Payable To | Payable At |
|-----------|----|----------|------------|------------|

3. Critical Dates

| | | | |
|--------------------------|---------------------|----------------------------|---------------------|
| Tender Publish Date | 03-10-2024 02:00 PM | Sale/Submission Start Date | |
| Download Start Date | | Sale/Download End Date | 25-10-2024 02:00 PM |
| Last Date of Application | 23-10-2024 02:00 PM | Last Date of Permission | |
| Last Date of Submission | 25-10-2024 02:00 PM | Tech Bid Opening Date | |
| Fin Bid Opening Date | | Tech Bid Uploading Date | |
| Uploading Bid Date Time | | Time | |

4. Pre-bid Meeting Details

| | | |
|------|-------|---------|
| Date | Venue | Address |
|------|-------|---------|

5. Work Details

| Sl No | Description | Estimated Cost (Rs.) | Completion Time | EMD (Rs.) |
|-------|---|----------------------|-----------------|------------------------|
| 1 | Repairing of Pump House at Headwork site of Kaijali Basty PWSS Under Alipurduar Division PHE DTE. | 93892 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 2 | Repairing of Pump House at 2nd TW site of Kaijali Basty PWSS Under Alipurduar Division PHE DTE. | 92144 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 3 | Repairing of Pump House at HW and 2nd TW site of SALSALABARI PWSS | 96884 | 60 DAYD | 2% OF ESTIMATED |

| | | | | |
|----|---|-------|---------|------------------------------|
| | Under Alipurduar Division PHE DTE. | | | AMOUNT |
| 4 | Repairing of Pump House at HW site and 2nd TW site of Jashodanga PWSS Under Alipurduar Division PHE DTE. | 96016 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 5 | Repairing of Pump House no1 at HW site of SAMUKTALA PWSS Under Alipurduar Division PHE DTE. | 96617 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 6 | Repairing of Pump House no 2 at HW site of SAMUKTALA PWSS Under Alipurduar Division PHE DTE. | 96115 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 7 | Repairing of Pump House at 2nd TW site of PURBA CHEPANI PWSS Under Alipurduar Division PHE DTE. | 85097 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 8 | Repairing of Pump House at 2nd TW site of BAKLA PWSS Under Alipurduar Division PHE DTE. | 95437 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 9 | Repairing of Pump House at 3rd site of BHATIBARI PWSS Under Alipurduar Division PHE DTE. | 96698 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 10 | Repairing of Pump House at 2nd site of SALKUMARHAT PWSS Under Alipurduar Division PHE DTE. | 78338 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 11 | Repairing of Pump House at 2nd TW site of TAPSHIKHATA PWSS Under Alipurduar Division PHE DTE. | 78338 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 12 | Repairing of Pump House at 2nd TW site of PAITKAPARA PWSS Under Alipurduar Division PHE DTE. | 78338 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 13 | Repairing of Pump House at 3rd site of DAKSHIN SONAPUR PWSS Under Alipurduar Division PHE DTE. | 82769 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 14 | Repairing of Pump House at HEADWORK site of PAITKAPARA PWSS Under Alipurduar Division PHE DTE. | 93791 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 15 | Repairing of Pump House at HEADWORK site of SALKUMARHAT PWSS Under Alipurduar Division PHE DTE. | 93791 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| | Repairing of Pump House at HEADWORK site of TAPSHIKHATA PWSS Under | | | 2% OF |

| | | | | |
|----|--|-------|---------|------------------------------|
| 16 | Alipurduar Division PHE DTE. | 93791 | 60 DAYD | ESTIMATED AMOUNT |
| 17 | Repairing of Pump House at HEADWORK site of BIRPARA (APD) PWSS Under Alipurduar Division PHE DTE. | 93791 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 18 | Repairing of Pump House at HEADWORK site of MUNSHIPARA PWSS Under Alipurduar Division PHE DTE. | 93791 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 19 | Repairing of Pump House at 2nd site of BIRPARA (APD) PWSS Under Alipurduar Division PHE DTE. | 78339 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 20 | Repairing of Pump House at 2nd TW site of MUNSHIPARA PWSS Under Alipurduar Division PHE DTE. | 78339 | 60 DAYD | 2% OF ESTIMATED AMOUNT |
| 21 | Repairing of Pump House and Boundary wall at Headwork site of Lokhnathpur PWSS Under Alipurduar Division PHE DTE. | 92727 | 60 DAYD | 2% OF ESTIMATED AMOUNT |

6. Attachments

| Sl No | File Name |
|-------|------------------------|
| 1 | SL3.pdf |
| 2 | SL5.pdf |
| 3 | SL1804102024203313.pdf |
| 4 | SL6.pdf |
| 5 | SL10.pdf |
| 6 | SL1704102024203410.pdf |
| 7 | SL7.pdf |
| 8 | SL9.pdf |
| 9 | SL2004102024203108.pdf |
| 10 | SL2104102024203016.pdf |
| 11 | ANNEXURE.pdf |
| 12 | SL1.pdf |
| 13 | SL1904102024203215.pdf |
| 14 | SL8.pdf |
| 15 | SL11.pdf |
| 16 | SL4.pdf |
| 17 | SL14.pdf |
| 18 | SL1504102024203552.pdf |

| | |
|----|-----------------------------|
| 19 | SL12.pdf |
| 20 | SL1604102024203503.pdf |
| 21 | SL2.pdf |
| 22 | Notice 1804102024202025.pdf |
| 23 | SL13.pdf |